

## Message Text

UNCLASSIFIED

PAGE 01 STATE 195716  
ORIGIN SY-05

INFO OCT-01 ARA-14 ISO-00 STE-01 /021 R

DRAFTED BY A/SY/OPS/T:E B SCHEELE:BAF  
APPROVED BY A/SY/OPS/T:C J PELCZYNSKI  
A/SY/OPS/T - B C RUNNER  
DESIRED DISTRIBUTION  
A/SY/OPS/FO/ARA

-----074942 031640Z /50

R 031505Z YUG 78  
FM SECSTATE WASHDC  
TO AMEMBASSY PANAMA  
INFO AMEMBASSY BUENOS AIRES

UNCLAS STATE 195716

PANAMA FOR OIC/RTC; BUENOS AIRES FOR RSO FROM A/SY/OPS/T

E.O. 11652: N/A

TAGS: ASEC

SUBJECT: COM VEHICLE BODY REPAIR WORK

REF: PANAMA 5332 (NOTAL)

1. RECOMMEND YOU EXPLORE POSSIBILITIES OF HAVING  
LOCAL REPAIR FACILITIES IN BUENOS AIRES ACCOMPLISH  
NEEDED BODY AND FENDER WORK FOR 1974 CHRYSLER, FULLY  
ARMORED COM VEHICLE.

2. PLEASE ADVISE SY/OPS/T REFEASIBILITY AND ESTIMATED  
COSTS. VANCE

UNCLASSIFIED

NNN

\*\*\* Current Handling Restrictions \*\*\* n/a

\*\*\* Current Classification \*\*\* UNCLASSIFIED

## Message Attributes

**Automatic Decaptioning:** X  
**Capture Date:** 01 jan 1994  
**Channel Indicators:** n/a  
**Current Classification:** UNCLASSIFIED  
**Concepts:** n/a  
**Control Number:** n/a  
**Copy:** SINGLE  
**Draft Date:** 03 aug 1978  
**Decaption Date:** 01 jan 1960  
**Decaption Note:**  
**Disposition Action:** n/a  
**Disposition Approved on Date:**  
**Disposition Case Number:** n/a  
**Disposition Comment:**  
**Disposition Date:** 01 jan 1960  
**Disposition Event:**  
**Disposition History:** n/a  
**Disposition Reason:**  
**Disposition Remarks:**  
**Document Number:** 1978STATE195716  
**Document Source:** CORE  
**Document Unique ID:** 00  
**Drafter:** E B SCHEELE:BAF  
**Enclosure:** n/a  
**Executive Order:** n/a  
**Errors:** n/a  
**Expiration:**  
**Film Number:** D780318-0530  
**Format:** TEL  
**From:** STATE  
**Handling Restrictions:** n/a  
**Image Path:**  
**ISecure:** 1  
**Legacy Key:** link1978/newtext/t197808115/aaaafokk.tel  
**Line Count:** 50  
**Litigation Code IDs:**  
**Litigation Codes:**  
**Litigation History:**  
**Locator:** TEXT ON MICROFILM, TEXT ON-LINE  
**Message ID:** efc4f759-c288-dd11-92da-001cc4696bcc  
**Office:** ORIGIN SY  
**Original Classification:** UNCLASSIFIED  
**Original Handling Restrictions:** n/a  
**Original Previous Classification:** n/a  
**Original Previous Handling Restrictions:** n/a  
**Page Count:** 1  
**Previous Channel Indicators:** n/a  
**Previous Classification:** n/a  
**Previous Handling Restrictions:** n/a  
**Reference:** 78 PANAMA 5332  
**Retention:** 0  
**Review Action:** RELEASED, APPROVED  
**Review Content Flags:**  
**Review Date:** 27 jun 2005  
**Review Event:**  
**Review Exemptions:** n/a  
**Review Media Identifier:**  
**Review Release Date:** n/a  
**Review Release Event:** n/a  
**Review Transfer Date:**  
**Review Withdrawn Fields:** n/a  
**SAS ID:** 1584732  
**Secure:** OPEN  
**Status:** <DBA CORRECTED> jms 970826  
**Subject:** COM VEHICLE BODY REPAIR WORK  
**TAGS:** ASEC  
**To:** PANAMA  
**Type:** TE  
**vdkgvwkey:** odbc://SAS/SAS.dbo.SAS\_Docs/efc4f759-c288-dd11-92da-001cc4696bcc  
**Review Markings:**  
Sheryl P. Walter  
Declassified/Released  
US Department of State  
EO Systematic Review  
20 Mar 2014  
**Markings:** Sheryl P. Walter Declassified/Released US Department of State EO Systematic Review 20 Mar 2014